

## VEHICLE INSPECTION REPORT

**YK70EFZ**

### Mercedes-Benz Sprinter 3.5t H2 Progressive Van

**Non Runner**  
Inspection

<b>Serious Damage?</b>	No	<b>Vehicle</b>	
		<b>VAT</b>	Plus VAT
		<b>V5</b>	Buyer To Apply

#### Details

<b>Reg. date</b>	03/12/2020	<b>Colour</b>	WHITE	<b>CAP Clean</b>	£11,900.00
<b>Year</b>	2020	<b>VIN</b>	W1V9076352P309021	<b>CAP Average</b>	£10,600.00
<b>Mileage</b>	TBC	<b>Body Style</b>	Panel Van	<b>CAP Below</b>	£8,675.00
<b>Fuel Type</b>	Diesel	<b>MOT Due</b>	Expired	<b>Gearbox</b>	MANUAL

\*NON RUNNER - DOES NOT START, GEARBOX ISSUES, PARTS REMOVED\* AD-BLUE, SIDE LOAD DOOR

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Unclassified  
Major Parts Missing  
Report Only



2: Unclassified  
Major Parts Missing  
Report Only





3: Bonnet  
Dented  
With Paint Damage



4: Bonnet  
Chipped  
Multiple Chips



5: Roof  
Dented  
With Paint Damage



6: Bumper Front  
Scratched  
Over 100mm Thru Paint



7: Wing nsf  
Dented  
With Paint Damage



8: Wing nsf  
Dented  
Over 30mm



9: Wing nsf  
Dented  
Over 30mm



10: Wing nsf  
Scratched  
Over 25mm Thru Paint



11: Door nsf  
Dented  
With Paint Damage



12: Door Moulding nsf  
Missing  
Replace



13: Door nsf  
Dented  
Over 30mm



14: Door nsf  
Dented  
Over 30mm





15: B Post ns  
Dented  
Over 30mm



16: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm



17: Qtr Panel nsr  
Dented  
Over 30mm



18: Qtr Panel nsr  
Hole  
Over 10mm



19: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



20: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



21: Qtr Panel nsr  
Dented  
Over 30mm



22: Unclassified  
Substantial Accident Damage  
Report Only



23: Qtr Panel nsr  
Dented  
Over 30mm



24: Door osr  
Dented  
With Paint Damage




25: Door osr  
Dented  
With Paint Damage



26: Badgedecal Rear  
Broken  
Replace





27: Door osr  
Dented  
Over 30mm



28: C Post os  
Scratched  
Over 25mm Thru Paint



29: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



30: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



31: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



32: Qtr Panel osr  
Dented  
With Paint Damage





33: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



34: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



35: Qtr Panel osr  
Dented  
With Paint Damage



36: Qtr Panel osr  
Dented  
Over 30mm



37: Qtr Panel osr  
Dented  
Over 30mm



38: Qtr Panel Moulding os  
Broken  
Replace



39: Door osf  
Dented  
Over 30mm



40: Door osf  
Dented  
Over 30mm



41: Door osf  
Dented  
With Paint Damage



42: Door Moulding osf  
Missing  
Replace



43: Door Moulding osf  
Missing  
Replace



44: Wing osf  
Dented  
Over 30mm





45: Bumper Front  
Hole  
Over 25mm



46: Wing osf  
Dented  
Over 30mm



47: Door Pad osf  
Soiled  
Heavy



48: Switches And Controls  
Missing  
Replace



49: Seat Base Cover osf  
Torn  
Over 3mm



50: Seat Base Cover nsf  
Soiled  
Heavy

## Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	Fault		